

Whirl Wind Aviation, Inc.
SERVICE LETTER

SL-200RV-040805

TO: ALL OWNERS / OPERATORS OF AFFECTED PROPELLERS
SUBJECT: BULKHEAD BRACKET INSPECTION
DATE: APRIL 8, 2005

MODELS All Whirl Wind 200RV Series propellers
AFFECTED:

REASON: Cracked bulkhead brackets discovered on two aircraft.

TIMELINE: Inspection is to be performed immediately.

DESCRIPTION OF INSPECTION:

1. Remove the spinner and inspect the steel bulkhead brackets for cracks.
2. Contact Whirl Wind Aviation if any cracks are discovered.
3. Remember to inspect the bulkhead brackets during the 50 hours inspection as outlined in in section 6.2 of the 200RV owner's manual.