

Whirl Wind Propellers Corp
SERVICE LETTER

SL-200C-061004

TO: ALL OWNERS / OPERATORS OF AFFECTED PROPELLERS
SUBJECT: PIN BASE REPLACEMENT
DATE: JUNE 10, 2004

MODELS AFFECTED: All Whirl Wind 200C Series propellers manufactured with serial numbers starting at 200C-240 and lower.

REASON: Propeller blade pin base may fail causing loss of pitch control and excessive vibration.

TIMELINE: This pin base replacement is recommended to be performed immediately.

DESCRIPTION OF REPLACEMENT:

1. Replacement of the current blade pin bases (2) with revised pin base must be performed for all affected propeller models.
2. **Who Can Do the Replacement:** This replacement can be performed by any certified propeller service center or by Whirl Wind Propellers Corp service center.
3. **Where to Obtain Replacement Parts:** Replacement pin bases available direct from Whirl Wind Propellers Corp.